

# General Environmental Incident Summary

**Incident:** 3577      **Date/Time Notice:** 12/1/2014      1320      **DEM Incident No:**  
**Responsible Party:** ONEOK Rockies Midstream  
**Date Incident:** 12/4/2014      **Time Incident:** 1200      **Duration:** 6 minutes  
**County:** McKenzie      **Twp:** 152      **Rng:** 98      **Sec:** 14      **Qtr:** NW NW NW  
**Lat:** 47.99183      **Long:** -103.19790      **Method:** Interpolation from map  
**Location Description:** Pipeline ROW south of CR10

**Submitted By:** Scott Merry      **Affiliation:**  
**Address:** 2217 12614 Ave NW  
**City:** Watford City      **State:** ND      **Zip:** 58854

## Received By:

**Contact Person:** Todd Kelvington  
2700 Lincoln Ave SE  
Sidney, ND 74103

**Distance Nearest Occupied Building:** 1 Miles      **Release Contained:** Yes

**Type of Incident:** Trackhoe turned over to the side

**Description of Released Contaminant:** Diesel Fuel

**Volume Spilled:** 1.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

## Cause of Incident:

While loading a trackhoe onto a flat trailer on the R.O.W. on unlevel ground, trackhoe slid off of trailer and rolled onto its side. Small amount of fluids were spilled.

## Risk Evaluation:

No immediate risk.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

No potential impact

## Action Taken or Planned:

The trackhoe was lifted upright and the spill ceased. The affected area was excavated, bagged and removed immediately.

**Wastes Disposal Location:** At an approved disposal facility.

## Agencies Involved:

## ***Updates***

---

***Date:*** 12/1/2014    ***Status:*** Reviewed - No Action Required

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Accident loading a trackhoe. Small volume spill that was immediately cleaned up. No followup necessary.